



TIME SPORT INTERNATIONAL announces United States RXS road pedal recall




Models Affected: RXS Titan Carbon, RXS Carbon, RXS and RXE sold between October 2004 and July 2006.

Pedals that are not subject to this recall have a gold dot on the underside of the pedal body just inside where the bearing cap is mounted to the pedal body, *see images below*.



Pedals with gold dot are not subject to this recall

2007 model pedals that do not have the racing clip are also not subject to this recall. *see images below*



Only pedals with the Racing Clip are subject to this recall

Pedals that have already been through the recall process have a red dot on the underside of the pedal body just inside where the bearing cap is mounted to the pedal body. *(image coming)*

Hazard: The threaded bearing cap can potentially come unthreaded from the pedal body and this can result in the pedal body coming off the pedal axle & bearing unit.

Remedy: Consumers should stop using the affected pedals immediately. Dealers and consumers should contact TIME SPORT INTERNATIONAL directly to arrange for the pedals to be inspected and, if necessary, to undergo repair.

Contact: For more information, contact TIME SPORT INTERNATIONAL at (800) 240-8051 starting October 2 2006, or send an e-mail to rxsrecall@timesportusa.com