

SAFETY RECALL

American Classic Ultralight Cassette Hub for Road or Mountain
manufactured January 1, 2005 - June 5, 2005

A manufacturing error in the cam plate may cause the cassette body to improperly engage. Could cause a rider to fall and this is the reason for the voluntary recall.



HOW TO IDENTIFY if your hub is subject to the recall:

First determine if the hub/wheel was purchased after January 1, 2005.

Then look at the outside of the hub shell for the serial number. The serial number is printed on the center of the hub shell opposite to the American Classic logo. The serial numbers involved in the recall start with the letter "S".

Do not ride the hub/rear wheel until the replacement cam plate is installed by your bike shop

American Classic will provide *free* replacement cam plates and instructions for hubs under the recall by calling the toll free recall line 1-800-345-8356 and have your serial number available.

Post until January 10, 2006

In Cooperation with the US Consumer Product Safety Commission