

IMPORTANT RECALL NOTICE

To: Customers

Performance, Inc. Announces Recall of:

Performance Forte 11 Tooth Derailleur Pulleys

Performance, Inc., of Chapel Hill, NC, is voluntarily recalling the Performance Forte 11 Tooth Derailleur Pulleys, item # 50-3013 UPC: 400011887056
400011887131.

These Forte derailleur pulleys were manufactured w bearings whose inside diameter is too large for the supplied brass bushings. The resulting wobble could cause the derailleur to miss shift and the chain to jam. Chain problems of this sort can impair the rider's ability to control his bike. If this happened he could lose control, fall and be injured.

We have received no reports of accidents or injuries.

The Forte Pulleys were only sold through Performance Stores, via the Performance web site: www.performancebike.com/shop and through Performance catalog sales.

They were sold from March 14, 2004 through to April 25, 2005.

Consumers should **stop using the pulleys immediately** and return them for replacement or refund. For refund, exchange or store credit, return them to the nearest Performance Store. Or for credit or exchange return to:

Performance Inc.
Attn: Returns Dept. (Pulley Recall)
1 Performance Way
Chapel Hill, NC 27514.

For more information call or write Performance Technical Product Support at:

800 553-TECH (8324) M-F 9am-10pm and Saturday 12-6pm (EST)
techsupport@performanceinc.com

or visit the company's website at <http://www.performancebike.com/>.

Gaynor Collester
Supervisor, Technical Product Support

