

Performance Xport Frame Adapter

Performance, Inc. Announces Recall of Performance Xport Frame Adapter, Item #: 40-1635

Performance, Inc., of Chapel Hill, NC, is voluntarily recalling the Performance Xport Frame Adapter. Some adapters have defective latching mechanisms. In the defective ones the seatpost hook and stem hook gates can come open in use. If this happens the bike may fall from the rack and be damaged.

The Xport Frame Adapters was only sold through Performance Stores, via the Performance web site: performancebike.com and through Performance catalogs.

They were sold from August 5, 2003 through to August 27, 2003.

Consumers should **stop using the frame adapters immediately** and return them for replacement or refund. For a refund or store credit return them to the nearest Performance Store. For credit or to exchange them for the Thule 982 Frame Adapter return to Performance Inc., Attn: Returns Dept. (Xpt Adapter Recall), 1 Performance Way, Chapel Hill, NC 27514.

For more information consumers can call Performance at 800 553-TECH (8324), Monday through Friday, 9 a.m. to 6 p.m. EST